



PRODUCT CHANGE NOTICE

JULY 27, 2009

| | |
|----------------------------|---|
| Notification Number | PCN 106 |
| Change Subject | Endura QZ35Q and JD35Q Product Change |
| Type of Change | Advisory |
| Key Milestone | Phased implementation beginning July 27, 2009 |

Change Description

The heatsink on the LAN 82566 chip is being removed to prevent a mechanical conflict while using a PCI card. The heatsink is an unnecessary component and is not needed for thermal management by the LAN chip. Photos of the heat sink (1) installed and (2) removed are show for your reference on the next page.

Customer Impact & Recommended Action

No action is required. The heatsink will be removed after existing inventory is shipped. There will be no rework of current inventory (removal of the heatsink). You may remove the LAN heatsink from the boards listed below and the RadiSys warranty will remain valid. If you have questions, please consult with your RadiSys FAE or contact RadiSys Technical Support.

Items Affected

| Product Code | Description | Current Part Number | New Part Number |
|--------------|------------------------------|---------------------|-----------------|
| JD1GO3-0-0 | JD35Q ATX Single GBE | 067-10081-0002 | 067-10081-0003 |
| JD2GO3-0-0 | JD35Q ATX Dual GBE | 067-10098-0002 | 067-10098-0003 |
| QZ1GO3-0-0 | QZ35Q UATX VGA | 067-10099-0002 | 067-10099-0003 |
| QZ2GO3-0-0 | QZ35Q UATX VGA, DVI, S-Video | 067-10100-0002 | 067-10100-0003 |

Revision History

| Date | Revision | Changes |
|----------|----------|-----------------|
| 07/27/09 | V1.0 | Initial Release |




Photo of board with LAN heatsink installed




Photo of board with LAN heatsink removed